



PRESS RELEASE

Las Vegas Metropolitan Police Department
Traffic Bureau
Collision Investigation Section - Fatal Detail
702-828-3535

Joseph Lombardo, Sheriff

REPORTING DETECTIVES: D. McCuiston, J. Pearson, N. Hoffman, M. Scanlon, Sgt. R. Stauffer
TYPE OF ACCIDENT: 3 Vehicle Collision
LOCATION OF ACCIDENT: West Spring Mountain Road/ South Decatur Boulevard
DATE OF ACCIDENT: 09/17/2021 **TIME:** 3:58 a.m. **EVENT #:** LLV210900071367

Number: 1	Driver: Robert Ferraro	Injury: Minor
	Address: East Haven, CT	Age: 34 Male
	Vehicle Information: 2020 Rolls Royce Cullinan	
	Passenger: Pending notification	Injury: Fatal
	Address: Pending notification	Age: 25 Male
	Passenger: Matthew Borges	Injury: Minor
	Address: Bethel, CT	Age: 32 Male
	Passenger: John Truhart	Injury: Minor
	Address: New Haven, CT	Age: 31 Male
	Passenger: Elizabeth Alvarez	Injury: Minor
	Address: San Antonio, TX	Age: 27 Female
	Passenger: Frida Navaro	Injury: Minor
	Address: San Antonio, TX	Age: 24 Female
Number: 2	Driver: Marcus Williams-Hayward	Injury: Minor
	Address: Hampton, VA	Age: 34 Male
	Vehicle Information: 2021 Ford Mustang	
Number: 3	Driver: Unoccupied	Injury: N/A
	Address: N/A	Age: N/A
	Vehicle Information: 2014 Scion XB	

COLLISION DETAILS:

On September 17, 2021, at approximately 3:58 a.m., a vehicle versus vehicle collision occurred near the intersection of West Spring Mountain Road and South Decatur Boulevard. Evidence at the scene, witness statements, and surveillance video of the collision indicted a white 2020 Rolls Royce Cullinan was traveling westbound on West Spring Mountain Road and entered the intersection with South Decatur Boulevard at a high rate of speed. The Rolls Royce began to lose control west of the intersection. A 2021 white Ford Mustang was facing southbound in the private drive of 4970 West Spring Mountain, waiting to enter the roadway. The Rolls Royce exited the roadway to the right, colliding with the Ford Mustang. The Rolls Royce continued westbound on West Spring Mountain Road and collided with roadside utility poles, landscaping, and a fire hydrant. The Rolls Royce overturned onto its roof, ejected the right front passenger from the vehicle, and up righted itself before coming to rest. Debris from the collision collided with a 2014 Scion XB that was parked, unoccupied at 5010 West Spring Mountain Road. Arriving medical personnel transported the passenger to University Medical Center's Trauma Unit. Despite all life-saving measures, the male passenger succumbed to his injuries. The driver of the Rolls Royce remained at the scene and showed signs of impairment. The driver was subsequently arrested for applicable charges. The passenger's death marks the 98th traffic-related fatality in the Las Vegas Metropolitan

Police Department's jurisdiction for the year 2021. The collision remains under investigation by the Las Vegas Metropolitan Police Department's Collision Investigation Section.